

TRANS CONTINENTAL CERTIFICATIONS PVT. LTD.

Certificate of Registration

This is to certify that

Quality Management Systems

of

BVishal Oil And Energy Limited

Opp. ONGC Colony, Highway Road, Palavasna, Mehsana - 384 003 (Gujarat) INDIA Other Sites Mentioned as per Annexure-Q

has been assessed and registered by TCCPL as conforming to the requirements of:

ISO 9001:2015

The Quality Management Systems is applicable to:

Providing Charter Hiring, Operations & Related Services for V-100-I (550 HP Work Over RiG), V-100-II (550 HP Work Over RiG) V-CTU-I, V-CTU-II, V-CTU-III, V-CTU-IV, V-CTU-V, V-Nitrogen-I, V-Nitrogen-II, V-Nitrogen-III, V-HOC-I, V-HOC-II, V-HOC-III, V-HOC-IV, WSS Units, V-SPF-I, V-SPF-II, V-SPF-III, V-SPF-IV, V-SPT-I, V-SPT-II Other Olifield Equipment

Certificate No: Q-9116113136

Certificate issue date : 16-11-2021 2nd Surveillance due date: 15-11-2023 Next Audit before: 15-11-2022

Re-Certification due date.: 15-11-2024

Managing Director







CB-MS-0702

TRANS CONTINENTAL CERTIFICATIONS PVT. LTD.

Website: www.tccplcertifications.com Email: info@tccplcertifications.com

Accredited by United Accreditation Foundation Inc. (UAF) Member of IAF

Lack of fulfilment of conditions set out for the issuance of this certificate and timely completion of periodic surveillance audit may render this certificate invalid

Certificate is the Property of TCCPL and shall be returned immediately when demanded



TRANS CONTINENTAL CERTIFICATIONS PVT. LTD.

Certificate of Registration

This is to certify that

Environmental Management Systems

of

BVishal Oil And Energy Limited

Opp. ONGC Colony, Highway Road, Palavasna, Mehsana - 384 003 (Gujarat) INDIA Other Sites Mentioned as per Annexure-E

has been assessed and registered by TCCPL as conforming to the requirements of:

ISO 14001:2015

The Environmental Management Systems is applicable to

Providing Charter Hiring, Operations & Related Services for V-100-I (550 HP Work Over RIG), V-100-II (550 HP Work Over RIG) V-CTU-I, V-CTU-II, V-CTU-III, V-CTU-IV, V-CTU-V, V-Nitrogen-I, V-Nitrogen-II, V-Nitrogen-III, V-HOC-I, V-HOC-II, V-HOC-III, V-HOC-IV, WSS Units, V-SPF-I, V-SPF-II, V-SPF-III, V-SPF-IV, V-SPT-I, V-SPT-II Other Oilfield Equipment

Certificate No: E-9116113137

Certificate issue date: 16-11-2021 2nd Surveillance due date: 15-11-2023 Next Audit before: 15-11-2022

Re-Certification due date.: 15-11-2024

Managing Director







CB-MS-0702

TRANS CONTINENTAL CERTIFICATIONS PVT. LTD.

Website: www.tccplcertifications.com Email: info@tccplcertifications.com

Accredited by United Accreditation Foundation Inc. (UAF) Member of IAF

Lack of fulfilment of conditions set out for the issuance of this certificate and timely completion of periodic surveillance audit may render this certificate invalid

Certificate is the Property of TCCPL and shall be returned immediately when demanded



TRANS CONTINENTAL CERTIFICATIONS PVT. LTD.

Certificate of Registration

This is to certify that

Occupational Health & Safety Management Systems

BVishal Oil And Energy Limited

Opp. ONGC Colony, Highway Road, Palavasna, Mehsana - 384 003 (Gujarat) INDIA Other Sites Mentioned as per Annexure-OM

has been assessed and registered by TCCPL as conforming to the requirements of:

ISO 45001:2018

The Occupational Health & Safety Management Systems is applicable to:

Providing Charter Hiring, Operations & Related Services for V-100-I (550 HP Work Over RIG), V-100-II (550 HP Work Over RIG) V-CTU-I, V-CTU-II, V-CTU-III, V-CTU-IV, V-CTU-V, V-Nitrogen-I, V-Nitrogen-II, V-Nitrogen-III, V-HOC-I, V-HOC-II, V-HOC-III, V-HOC-IV, WSS Units, V-SPF-I, V-SPF-II, V-SPF-III, V-SPF-IV, V-SPT-I, V-SPT-II Other Oilfield Equipment

Certificate No: OM-9116113138

Certificate issue date: 16-11-2021

Next Audit before: 16-11-2022

2nd Surveillance due date: 16-11-2023

Re-Certification due date.: 16-11-2024

Managing Director







TRANS CONTINENTAL CERTIFICATIONS PVT. LTD.

Website: www.tccplcertifications.com Email: info@tccplcertifications.com

Accredited by United Accreditation Foundation Inc. (UAF) Member of IAF

Lack of fulfilment of conditions set out for the issuance of this certificate and timely completion of periodic surveillance audit may render this certificate invalid

Certificate is the Property of TCCPL and shall be returned immediately when demanded